

## **Digital in/outdoor thermo-hygrometer operating instructions specifications**

- 1) Measuring in/outdoor Temperature Range:  $-50^{\circ}\text{C}\sim 70^{\circ}\text{C}$  ( $-58^{\circ}\text{F}\sim +158^{\circ}\text{F}$ ).
- 2) Measuring in/outdoor humidity range: 10%RH-99%RH.
- 3) Temperature Accuracy:  $\pm 1^{\circ}\text{C}$  ( $\pm 2^{\circ}\text{F}$ ), humidity accuracy:  $\pm 5\%$  RH.
- 4) Temperature Display Resolution:  $0.1^{\circ}\text{C}$  ( $0.1^{\circ}\text{F}$ )
- 5) humidity display resolution 1%RH.
- 6) selectable temperature unit:  $^{\circ}\text{C}$  or  $^{\circ}\text{F}$ .
- 7) recording MAX/MIN temperature value automatically.

### **Buttons&operations**

#### **2.MIN/MAX (IN) button**

Press MIN/MAX (IN) key will display the minimum indoor temperature and minimum indoor humidity.

Press MIN/MAX Key(IN) key again will display the maximum indoor temperature and maximum indoor humidity.

Press MAX/MIN (IN)key and hold the key last 3 seconds to reset the maximum indoor temperature and maximum indoor humidity value .

#### **2.MIN/MAX(OUT) button**

Press MIN/MAX (OUT) key will display the minimum outdoor temperature and minimum outdoor humidity.

Press MIN/MAX (OUT)key again will display the maximum outdoor temperature and maximum outdoor humidity.

Press MAX/MIN (OUT)key and hold the key last 3 seconds to reset the maximum indoor temperature and maximum indoor humidity value.

#### **3. $^{\circ}\text{C}$ and $^{\circ}\text{F}$ button**

On the back of the product you can press the  $^{\circ}\text{C}/^{\circ}\text{F}$  to choose  $^{\circ}\text{C}$  or  $^{\circ}\text{F}$  .